

UKMTO Advisory – Electronic interference in the Strait of Hormuz



With thanks to UKMTO the Club would like to bring to the attention of Members [UKMTO Advisory 006-25](#) dated 10th March 2025 which highlights corroborated reports from vessels experiencing GPS interference in the Strait of Hormuz.

Members should consider this information for navigation planning purposes and implement appropriate mitigating measures to ensure safety of navigation in the event of possible failure or loss of GPS Satellite signal reception. The Master and watchkeeping officers should be thoroughly familiar with alternative means of plotting and monitoring their vessel's position, keeping in mind the potential limitations of their vessel's navigational equipment.

Masters who experience disruption to electronic navigation systems anywhere within the UKMTO Voluntary Reporting Area (VRA) are requested to contact UKMTO watchkeepers via watchkeepers@ukmto.org or 02392 222065.

Supportive Information

For further information on this or other Loss Prevention topics please contact the Loss Prevention Department, Steamship Insurance Management Services Ltd.

Tel: +44 20 7247 5490;

Email: loss.prevention@simsl.com

Resources:

[IN15 - UKMTO Advisory 006-25: Electronic interference in the SoH](#)

[UKMTO Advisory Incident 006-25: Electronic interference](#)